



QUICK CHANGE TAPPING ATTACHMENT TYPE QSFL (NON REVERSIBLE)

Q : Quick Change (Tap Adaptor)

S : Safety Clutch

F : Float Radial Parallel

L : Length Compensation

Application :

For Tapping operation on Drilling , Tapping and Radial Drilling machines. For Horizontal application on Lathes.

Features :

Quick Change Tapping Attachment to be used with Quick Change Tap Adaptors KWE1 / KWE2.

Adjustable Safety Clutch Prevents Tap Breakages.

Length compensation acting on compression and expansion to compensate between the tap pitch and machine or hand feed.

Self - centering Radial Parallel float to compensate misalignment between the tap and hole to be tapped.

