



Quick Change Tapping Chucks Type KWFSL 60(M 30 to M 120)

Application:

For tapping operations with single pass and series taps on mechanically and numerically controlled radial drilling machines, drilling and milling machines.

Features:

Quick change system with automatic locking of the adaptor in the chuck.

Adjustable length compensation acting on compression and expansion to compensate for differences between spindle feed and tap pitch.

Adjustable safety clutch with minimum torque after disengagement to protect against tap breakage.

Interchangeable shanks to allow the use of the chuck on different machines spindle configurations.

For lefthand threads on request.

